

Cambelt Change Intervals - Diesel Engines



The contents of this Information Update are confidential and for Volkswagen Authorised Repairers internal use only. It should not be passed to third parties. It is a breach of your Authorised Repairer Agreement to pass technical advice provided by Volkswagen UK to third parties. Should an independent third party repairer request details of technical information, please refer to Information Update 345/03.

Latest change	Model	Engine	Engine code	Period	Change intervals	Also to be changed
11.01/Li	Lupo, Polo	1.2, 1.4, 1.9 PD	ANY / AMF / AYZ	Up to 00 MY	40,000 miles	Belt idler
				From 01 MY	60,000 miles	
			BAY	From 01 MY	60,000 miles	Belt idler
05.05/Li	Lupo, Polo, Fox	1.2, 1.4, 1.9 PD	BAY / AMF / AXR / ATD / ASZ / BLT / BNM / BNV	From 04 MY	80,000 miles	Belt idler Every 160,000 miles
12.00/Li	Lupo, Polo	1.7 SDI	AHG / AKU	Up to 00 MY	40,000 miles	
				From 01 MY	60,000 miles	
		1.7 SDI	ASY	From 01 MY	60,000 miles	
11.01/Li	Polo	1.9 SDI	AGD / ASX	From launch	60,000 miles	
	Polo	1.9 SDI	ASY	From launch	80,000 miles	Idler no. 038 109 244 H, once at 80,000 miles part replaced with 038 109 244 M
08.02/Li	Polo	1.9 SDI	ASY	From 03 MY	90,000 miles	
03.00/Li	Polo Classic/ Variant	1.7 SDI	AKW	From launch	40,000 miles	
01.02/Li	Polo Classic/ Variant	1.9 SDI/TDI	AHB / AEY / AHU / ALE / AFN	From launch	60,000 miles	
	Polo Classic/ Variant	1.9 SDI/TDI	AGP / AQM / ALH / AGR / ASK / ASV / AYQ	Up to 01 MY	60,000 miles	
12.01/Li	Polo Classic/ Variant	1.9 SDI/TDI		From 02 MY	80,000 miles	Idler no. 038 109 244 H, once at 80,000 miles part replaced with 038 109 244 M
12.00/Li	Golf, Vento	1.9 SDI	AEY	From launch	60,000 miles	
12.00/Li	Golf, Vento	1.9 TDI	1Z / AFN / AHU / ALE	From launch	60,000 miles	
08.02/Li	Golf Mk IV/Bora/New Beetle	1.9 SDI/TDI	AGP / AQM / ALH / AGR / AHF / ASV	Up to 01 MY	60,000 miles	
				From 02 MY	80,000 miles	Idler no. 038 109 244 H, once at 80,000 miles part replaced with 038 109 244 M
				From 03 MY	90,000 miles	
02.02/Li	Golf Mk IV/Bora/New Beetle	1.9 TDI PD	AJM	Up to 00 MY	40,000 miles	Belt idler

	Golf Mk IV/Bora/New Beetle	1.9 TDI PD	AJM	From 01 MY	60,000 miles	Belt idler
	Golf Mk IV/Bora/New Beetle	1.9 TDI PD	ASZ / AXR / AUY / ATD / ARL	From launch	60,000 miles	Belt idler
05.03/Li	Golf Mk IV/Bora/New Beetle	1.9 TDI PD	ASZ / AXR / ATD / ARL / BEW	From 04 MY	80,000 miles	Belt idler
05.05/Li	Golf Mk V/Touran/ Golf Plus	TDI - PD	AVQ / AZV / BKD / BKC / BDK / BRU / BJB / BLS / BMM	From launch	80,000 miles	Belt idler every 160,000 miles
05.00/Li	Passat	1.9 TDI	1Z / AFN / AHU / AVG / AHH	From launch	60,000 miles	
02.03/Li	Passat	2.5 V6 TDI	AFB / AKN	From 99 MY	80,000 miles	
08.03/Li	Passat	2.5 V6 TDI	BDH / BAU / BDG	From launch	80,000 miles	Belt idler no. 059 109 243 L
12.00/Li	Passat	1.9 TDI PD	AJM	Up to 00 MY	40,000 miles	Belt idler
				From 01 MY	60,000 miles	Belt idler
02.01/Li	Passat	1.9 TDI PD	ATJ / AVB / AVF / AWX	From launch	60,000 miles	Belt idler
05.03/Li	Passat	1.9 TDI PD	AVB / AVF / AWX	From 04 MY	80,000 miles	Belt idler
05.04/Li	Passat	2.0 TDI	BGW / BHW	From Launch	80,000 miles	Every 160,000 miles
05.05	Passat B6	TDI-PD	BKC / BKP / BLS / BMA / BMP / BMR / BVE	From Launch		
05.05/Li	Sharan	1.9 TDI	1Z / AFN / AVG / AHU	From launch	60,000 miles	
	Sharan	1.9 TDI PD	ANU / AUY	From launch	40,000 miles	Belt idler
	Sharan	1.9 TDI PD	ASZ / BRT / BTB	From 04 MY	60,000 miles	Every 120,000 miles
	Sharan	1.9 TDI PD	ASZ / BRT / BTB	From launch	60,000 miles	Belt idler

Please note that these are the manufacturer's recommended change intervals. This information applies to vehicles from 97 model year onwards.

Always refer to Information Update 334/05, ELSA and ETKA.

Version 25